

Waiapu Cathedral of St. John the Evangelist, Napier

Seismic Risk Report



12 June 2023

Contents

1.	Purpose	3
2.	Basis of this Report	3
3.	Description of Building	4
4.	Summary of Seismic Assessment	5
5.	Evaluation of Current Seismic Risk	5
6.	Impact of Closure	7
7.	Summary and Recommendations	8
Арре	endix: Application of the BRANZ Decision-making Framework for Earthquake-prone Buildings	10

Document Status and Authorisation

Stage	Person	Date
Draft prepared by:	Dave Brunsdon	8 May 2023
Update following discussion with Diocese Earthquake Strengthening Committee:	Dave Brunsdon	29 May 2023
Final version:	Dave Brunsdon	12 June 2023

1. Purpose

This seismic risk report summarises known seismic information on the Cathedral structure from recent work by WSP. The report provides a qualitative risk assessment which evaluates the current seismic risk to occupants and users of the building and people in surrounding areas.

The purpose of the report is to outline the current seismic risk profile to assist decisionmaking in relation to continued use while broader planning about the future of the building is undertaken.

Recommendations are made in relation to continued occupancy, any practical short-term risk mitigation measures are identified and key communications messages outlined.

The qualitative risk assessment undertaken is supported by the application of the 2021 BRANZ Decision-making Framework for Earthquake-prone Buildings for council-owned buildings (refer to the appended Risk Evaluation Table).

2. Basis of this Report

Engineering assessment reports	Detailed Seismic Assessment by WSP - 7 December 2021
Kestrel inspection of the building	10 May 2023
Discussions with Diocese Earthquake Strengthening Committee	24 May 2023
Other information as relevant	Nothing specific

3. Description of Building

Date of construction	The building comprises several interconnected sections that were constructed in three stages between 1956 and 1960.
Number of storeys	The Bell Tower is approximately 40m high; the Chancel and Nave have a roof ridge of approximately 23m; the Chapel has a roof ridge height of approximately 11m; and there are associated connected single storey structures on the sides of the main building.
MBIE EPB Profile Category	Profile Category B – equivalent of three or more storeys (12m) in height, pre-1976.
Primary structure	Reinforced concrete
Secondary structure (incl. heavy non-structural elements)	Roofing tiles above the Nave and Chancel.
Current Usage	Workplace for Admin personnel. Used for weekly services and meetings; periodically for larger funerals and weddings, concerts and events and tourist groups.
Importance Level	Importance Level 3 (IL3) - Public assembly building with an area greater than 1000m ² and groups of greater than 300 people.



4. Summary of Seismic Assessment

Form and date of assessment	Detailed Seismic Assessment by WSP dated December 2021	
Rating and Critical Structural Weaknesses	 The overall rating for the building is 20%NBS (IL3). The component scores and identified Structural Weaknesses are: 20%NBS for the Bell Tower (lack of strength of slender walls with large openings at the base of the tower); 20%NBS for the Nave (lack of strength of the end piers and internal piers, and roof level eaves beams); 25%NBS for the Vestry (lack of strength of internal piers); 30%NBS for the Chancel (lack of strength of internal piers) 	
Earthquake prone status/ council notification and expiry date	A copy of the December 2021 WSP DSA was forwarded to Napier City Council in 2022. An EPB notice has yet to be issued by NCC to the Diocese, and so the applicable statutory time period of 15 years has yet to commence.	

5. Evaluation of Current Seismic Risk

	Maximum number of people:	Up to a maximum of 650 people in the main church areas at major events (~20 per year) for a period of up to 4 hours
Current usage	Maximum weekly occupancy:	~100 people at Sunday morning service
characteristics	Average number of people during weekday:	Gatherings of approx. 10 in the main church (during the day) and 10 to 30 in the Lounge/ Choir room for 1 to 2 hours at a time. Staff in offices – 4 to 6
	Average weekly usage time:	600 to 700 person hours per week

Summary of main structural vulnerabilities	The lower section of the Bell Tower is highly loaded in an earthquake due to a combination of the slender walls and large openings, and has a corresponding low level of strength to resist strong ground shaking. The piers in the walls of the Nave, Chancel and Vestry are also tall and slender, with limited lateral strength. With no diagonal bracing, the roof of the Nave has limited stiffness and strength to tie the walls together and transfer loads to the end walls. There is also no bracing within the roof sub-structure above the ceiling of the Nave. Neither the building or any part of it is identified as dangerous in terms of the Building Act.
Outline of possible failure modes	 In the event of a large earthquake, the following failure modes are possible: Collapse of the Bell Tower, with the potential for the upper part of the tower to fall outside the property boundary Failure of sections of the end and side walls of the Nave (depending on the direction of the earthquake), which could in turn lead to collapse of part of the roof Similar failures could occur in the middle sections of the Chancel and Vestry walls It is considered unlikely that all of these failure modes would occur in the one earthquake.
Summary of strengthening options	The main roof sub-structure of the Nave can have steel bracing added within the ceiling space to provide strength above ceiling level both across and along the building. The Bell Tower walls could be strengthened by providing additional strength to the lower levels of the walls. Reducing the height of the Bell Tower is an alternative option, but in itself would not address the vulnerabilities in the main structure of the remainder of the cathedral. The Nave, Chancel and Vestry could be strengthened by the addition of steel framing at the roof-to-wall connections and jacketing the inside of the perimeter walls.

Interim risk mitigation options	The size of the building and the identified vulnerabilities to many of the walls of the structure mean that there are limited opportunities for local interim mitigation work. The WSP recommendation of a comprehensive audit of the non-structural items (incl. the organ, suspended cross and various statues) is endorsed. The provision of additional restraint to these elements would reduce the risk to occupants in more moderate earthquakes.
Seismic Hazard	The building is located in an area of High Seismic Hazard. This is influenced by the proximity of the Hikurangi Subduction Zone – the interface whether the Pacific and Australian plates meet. The likelihood of a fault rupture occurring on this interface and generating an earthquake of greater than Magnitude 8 is 26% in the next 50 years. An earthquake of this magnitude would cause significant damage to the Cathedral. The likelihood of an earthquake of this scale occurring in any given year, or over a 5 to 10 year period, is correspondingly much lower.
Intended time frame for seismic risk to be addressed	Not yet determined – when NCC issue the Earthquake Prone Building notice, a period of 15 years will apply.

6. Impacts of Closure

Ability to use other facilities	Other off-site facilities could be used for meetings and small church services, but none are of comparable size. For large church services or other functions, the key features of the Cathedral could not be replicated elsewhere. The quiet and large open space within the Cathedral also provides a place of refuge and sanctuary, for both the
	Congregation and the wider public.
	more than a short period is likely to create uncertainty amongst the congregation. It is considered that this uncertainty would lead to members leaving the church permanently.
Effects on the community	The Aotearoa Chapel has a large significance to iwi, with associated impacts if no longer able to be accessed for any period of time.
	There would also be other impacts on the wider community, including the homeless community who see the Cathedral as an alternative home. Tourists would also be unable to view the interior.

Costs and economic impacts	Closure of the Cathedral would lead to a loss of income from hireage and tithes from parishioners and donations from visitors. There would also be an adverse impact on bequests. This would only be offset to a small degree by a reduction in operating costs.
	If closed for any period of time, it is considered that the impacts on the Diocese (both the organisation and the congregation) is such that it would be unable to be re-opened.

7. Summary and Recommendations

	The likelihood of an earthquake of sufficient magnitude to cause structural failure to the building (or major parts) over the next few years while plans for strengthening are being developed is considered very low. It is therefore considered that continued occupancy and use of the building is appropriate while plans for the building are
Occupancy recommendations	being developed and implemented. An indicative timeline should however be developed and actively monitored.
	Given the relatively uniform nature of the risk across all sections of the Cathedral and the short-term nature of access to and use of the Bell Tower, it is not considered necessary to continue with the current access restrictions.
	Staff and regular users of the building should be briefed on the seismic status of the building, including a refresh of the earthquake drills and evacuation process.
Required actions	This should be included in the induction of new staff. Other people accessing the building should be briefed through Council's EPB notices (when issued) that should be placed immediately adjacent to all entrances. Prior to receiving Council's EPB notices, the Diocese should prepare and display its own risk notification placards.
	The building has a low seismic rating due to the presence of structural weaknesses in the walls, including the Bell Tower.
Key communications messages	The building is not dangerous in terms of the Building Act, or in any imminent risk of failure in a moderate earthquake.
	In the unlikely event of an earthquake occurring, people should stay inside the building and not leave the building until

	after all shaking has ceased and the all-clear to exit the building has been given.
	Refer to the occupancy recommendations above.
Annual monitoring	There should be a review in June of each year which revisits the condition of the building, verifies that the EPB notices are effectively displayed and provides a written update on progress with planning for the seismic remediation of the building.



Appendix: Application of the BRANZ Decision-making Framework for Earthquake-prone Buildings

Date of Risk Evaluation: 26 May 2023

Step	Considerations	Information/ Comments	
	The seismic assessment is a Detailed Seismic Assessment?	Yes	
	Report status and nature of review undertaken?	Final report. No full Peer Review undertaken	
	Seismic rating?	20%NBS (IL3)	
Step 1: Building assessment and further examination of key vulnerabilities	Have all secondary structural and heavy non-structural elements been identified?	Yes, but require further more specific investigation	
	What are the structural elements of the building that	The lower section of the Bell Tower is highly loaded due to a combination of the slender walls and large openings, and has a corresponding low level of strength to resist earthquakes.	
		The piers in the walls of the Nave, Chancel and Vestry are also tall and slender, with limited lateral strength.	
	What are the modes of failure and the area of the building that is affected?	 In the event of a large earthquake, the following failure modes are possible: Collapse of the Bell Tower, with the potential for the upper part of the tower to fall outside the property boundary (review the openings in the base of the tower) Failure of sections of the end and side walls of the Nave, which could in turn lead to collapse of part of the roof Similar failures could occur in the middle sections of the Chancel and Vestry walls It is considered unlikely that all of these failure modes would occur in the one earthquake. 	
	Are there other seismic vulnerabilities that score above 34%NBS?	No	
	Is the building or any part of it identified as dangerous in terms of the Building Act?	No	

Step	Considerations (Using the tables from	Comments and Rating	
	Table 1 Life safety risk exposure		
Step 2: Exposure of people to building risk	Life safety risk exposure ca		
	High	Moderate Low	
	Maximum number of people in building at >100 any time	10-100 <10	Max occupants: 650
	Average number of people in building at >50 any one time	5-50 <5	Avge occupants: <50
	Average user time in building (duration Over 8 hours a day of use)	2-8 hours a day	Avge user time: ~2 hours
	Average weekly usage (person-hours per >2,000 week)	50-2,000 <50	Avge weekly usage: 600-700 person hours
	Exposure to people outside the building use footpath (>100 people per hour); risk of collapse onto peiptbouring	Risk of collapse onto adjacent moderate- use footpath (5-100 per hour)	External exposure: Some external collapse risk to road and neighbouring property
	structure		Rating: High
	Table 2 Period of exposure		
Step 3: Risk mitigation measures – period of exposure	Period of exposure catego	ory	High seismic hazard zone
	Seismic hazard zone	ledium Short	The planning of strengthening work is likely to
	Likely period until High >3 years 1	-3 years <1 year	take more than 3 years
	commenced Medium >o years 2	-6 years <2 years	
	Low >9 years 3	-9 years <3 years	
			Category:Long

	Table 3 Degree of expo	sure			
Overall Exposure	Exposure to risk (from Table 1)	Period of e	exposure (from Table 2)		
	Low	Snort	Medium	Long	
	LUW	1	1		
	High	1			
				\smile	
					➢ Rating: Ⅲ
	Table 4 Consequence of closure				
		Consequence of closure category			Smaller services could be delivered in other
Step 4: Consequences of building closure		High	Moderate	Low	locations, but not large services
	Ability to deliver services by other means	Service cannot be delivered through alternative means	Service can be partially delivered out ide of the building	Service easily delivered through other means	Some impact on vulnerable communities
	Impact on vulnerable communities (homeless, disabled, high needs, children, elderly)	Vulnerable community significantly impacted as they cannot be easily catered for	Vulnerable community impacted but services/ amenities can be found nearby	Limited or no vulnerable community use the building/services	Significant impact on Diocese revenue
	Impact on neighbouring businesses	Neighbouring businesses significantly impacted by direct loss of customers	Neighbouring business affected by reduced foot traffic	Limited or no impact on neighbouring businesses	Limited impact on neighbouring businesses
	Impact on staff	Significant numbers of staff affected by closure	Some staff notably impacted by building closure	Few or no staff impacted	A number of staff would be impacted
					Category:Moderate
	Table 5 Overall assess	ment			
Step 5: Overall assessment of building risk	Consequences of closure (Table 4)				
	Degree of exposure to risk (Table	usure to risk (Table 3) High Moderate Low > Overall risk rating: B – remain		Overall risk rating: B – remain open	
		A	В	C	
		_	\bigcirc		